

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001534**Date Inspected:** 25-Feb-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 600**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1330**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China

<b>CWI Name:</b>	Cui Yi Ru	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	OBG	

**Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector Tim McClendon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

The QA Inspector witnessed ZPMC welder Hong Yong Li certification number 044801 depositing filler metal on web plate to floor beam number FB004-01 weld number 021 and weld number 007 utilizing the Flux Cored Arc Welding (FCAW) process using welding procedure WPS-B-T-2132-3. ZPMC Certified Welding Inspector (CWI) Cui Yi Ru Certification Number 00072221 and ZPMC Quality Control Inspector (QC) Zhu Tian Shu was observed monitoring and recording the following weld parameters for weld number 021 Amperage 297, Volts 29, Travel Speed 451mm/minute, temperature 62°C and for weld number 001 Amperage 298, Volts 29, Travel Speed 446mm/minute, temperature 68°C. The QA inspector also monitored welding parameters and the findings concur with ZPMC CWI and QC's results, and appear to comply with approved WPS.

**Summary of Conversations:**

No relevant conversations spoken on this date.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

<b>Inspected By:</b>	McClendon,Timothy	Quality Assurance Inspector
<b>Reviewed By:</b>	Cuellar,Robert	QA Reviewer

---